

	Industrial Site Services Co. Ltd	Issue Date: March 2016
	Safe Operating Procedures – Beam Clamp	Authorised By: HSE Manager
Uncontrolled if Printed		

DO NOT use this machine unless you are trained in its safe operation and have been given permission by a supervisor



Safety glasses must be worn at all times in work areas



Long and loose hair must be contained



Safety footwear must be worn at all times in work areas



Close fitting/protective clothing must be worn

Pre-Operational Safety Checks

1. For wear on hooks of clamps
2. That the adjustment pin works

Operational Safety Checks

1. Clamp is secured on tight to beam.
2. Anything hanging off the beam clamp is in a vertical direction.

Do not Overload the weight on the clamp

Do not Hang from the clamp

Housekeeping

1. Do not leave clamps lying around when finished with them

Potential Hazards

- Someone could trip over them
- They could fall from the beam and hit someone