

	Industrial Site Services Co. Ltd	Issue Date: 15 June 2018
	Safe Operating Procedures – TIRFOR	Authorised By: Stores
Uncontrolled if Printed		

DO NOT use this machine unless you are trained in its safe operation and have been given permission by a supervisor



Safety glasses must be worn at all times



Long and loose hair must be contained



Sturdy footwear must be worn at all times



Close fitting/protective clothing must be worn at all times



Rings and jewellery must not be worn

Pre-Operational Safety Checks

1. Check that the wire is in good condition
2. Check that the anchor pin isn't damaged
3. Make sure levers are functional
4. Make sure you have the right size wire to fit the Tirfor
5. Make sure the safety latch is on its hook
6. Check excessive wear and tear

Operational Safety Checks

1. Hooks should be distortion and safety latch operational

Forbidden

- Do not** Disengage the neutral lever while tirfor is under load.
- Do not** Use over loads capacity
- Do not** Lift or lower persons

Housekeeping

1. Ensure that that wire is properly wrapped after use.
2. Keep clean from dust and dirt

Potential Hazards

- Rotating equipment
- Wire rope breakages
- Incorrect anchor for load
- Tripping over the wire